



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor

Ted Stewart
Executive Director

James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

M/037/028

November 9, 1995

TO: Minerals File

FROM: Tony Gallegos, Reclamation Engineer *adg*

RE: Site Inspection, Energy Fuels Nuclear, MiVida Mine, M/037/028, San Juan County, Utah

Date of Inspection: November 2, 1995
Time of Inspection: 1400
Conditions: Clear skies, cool temperatures
Participants: Tony Gallegos, DOGM

Purpose of Inspection: To examine the site while in the area


This inspection was a brief drive-by inspection. The paved access road which leads through the site has some significant erosion gullies in it before reaching the mine site. These are near what has been called the lower MiVida site. Photographs were taken of the lower portion of the site, which includes the McCormick Tunnel and dump.

The backfilled shaft at the upper portion of the Mi Vida site appears to be stable. This shaft had slumped in after some of the reclamation work. It doesn't appear that this has happened again. Photographs were taken of this area as well. In addition, photographs were taken looking down over the upper portion of the MiVida site to compare with previous photos and also show the revegetation progression.

The dirt road which continues on past the upper portion of the MiVida site looks as if it has been bladed recently. This may be a county road which goes through to the other side.

jb
cc: Roger Smith, Energy Fuels
M037028.ins





11/11/11

0201/1001/11



m/037/028



M. VIDA

